

TENNESSEE DEPARTMENT OF TRANSPORTATION EROSION PREVENTION/SEDIMENT CONTROL INSPECTION REPORT

TDOT EPSC INSPECTION FORM Rev. Feb 2010

Reason For Inspection:

1st Weekly

2nd Weekly

											DATE:	10	20-11	
State Route	(SR) / US Rou	ile or Road Na	ime and De	scription:			Are correcti	ve actions	required by t	his inspec	clion report ((Y/N):		
		Wolf	River Blvd.						YE	5				
County(ies):		TDOT PIN:		NPDES Permit (NOC) #:			Number of I	New	Number of F	Recurring	Number of	New	Number of Un-C	orrected
SI	nelby	1016	15	7	ΓNR153299		Corrective /	Actions:	Corrective A	Actions:	Sediment f	Releases.	Sediment Releas	ses:
TDOT Cons	truction No.:	TDOT Contra	ct No.:	Contractor:										
7994-	1535-54		· 10 • • • • • • • • • • • • • • • • • •	Acuff	Enterprises	s Inc.]	a e	1					
I certify, unde	er penally of law	that this docum	ent and all a	ttachments w	vere	COG EPS	C Inspector :	and Title (n	rint or type):		Signature:			
prepared und	ler my direction of	or supervision in	accordance	e with a syste	em	000 2.0	o mopooto.	απα τητο (ρ	(,, 1,50).		G,g,,G,taro.			
information p	ssure that qualif	d on my inquiry	of the perso	n or persons	who		Geral	ld "Jerry" S	tanfill		Sei	all.	Stanfie	9
information 1	syslem, or those cerify that inspe	persons airecti	y responsible	e for galherin	ig the	Contractor	EPSC Inspi	eclor and T	itle (print or	type):	Signature:			
of erosion an above. I cert	d sediment cont lify that erosion a	rols have been and sediment co	performed a ontrols in the	s recorded in drainage are	n lhe table ea of the			Tom Acuff			1			
identified out	fall where installe he table above. I	ed as planned a	and designed	I in working o	order as	COC ERC	C Project Ma				Signature:	m V	1001)	
submitting (a	lse information, i	i am aware mac including the po	mere are signs sibility of fire	gnilicant pena ne and impre	sonment for	(print or ty		anayer	Commence of the commence of th		- Signature.			
knowing viola						(print or ty		mothy Bier	dz		1/54	AB.		
											0	1	1	
		TDOT EPSC					т			TD 0710			, F) (
5.	0 ()4(Predicted	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall	D	NO NO		7	nspection Report	
Date	Day of Week		Gauge 1	Gauge 2	Gauge 3	Gauge 4	Gauge 5	Gauge 6	Duration	8.75	or olain and init	YES)		
	Cunday	(%)	(in)	(in)	(in)	(in)	(in)	(in)	(hr)			1 0	11-	
1- 1- 11	Sunday	10			N/A	N/A	N/A	N/A		·2H -	Schop		of for lower	Tow
10-17-11	Monday	10	0	0	N/A	N/A	N/A	N/A	1.5	- H -	Has de	een (compressed.	
10.18.11	Tuesday	80	0,20	0.10	N/A	N/A	N/A	N/A	3.0					
10.19.11	Wednesday	0	0.30	0.40	N/A	N/A	N/A	N/A	3,0.					
10-20-11	Thursday	0	0	0	N/A	N/A	N/A	N/A	-					
1021.11	Friday	6			N/A	N/A	N/A	N/A						
10.2211	Saturday	0			N/A	N/A	N/A	N/A						
10123.11	Sunday	30			N/A	N/A	N/A	N/A					***	

Predicted Precipitation Source:

www.weather.com

Page 1 of 8

(Additional pages may be attached, if needed)

SEW SE	ACRI	THE XX	STORE TO A	
1	1	796		<i>y.</i>

State/US Route or Road Name:	Wolf River Blvd.

TDOT	Cone	truction	No.
1001	CUID	แนนแบบ	INU

	7-54

TDOT Contract No.:

CONDITION CODES

Date	10/20/2011	

5B	1	50+00	RT	10/13/2011		9,16	FM	Monitoring BMP's in place.
5A	1	49+00	RT	10/13/2011		16	FM	Monitoring BMP's in place.
4	1	40+00	RT	10/17/2011	0.00	15,16,33,43	I,RO	85% of rip-rap in place. Re-Hydro seed disturbed area. Stabilize slope. See Photos
3	1	34+50	LT					The area has not been disturbed.
2B	1	35+50	LT	10/20/2011		16,24	FM	Weekly cleaning for stream crossing required, until further notice. BMP's needed. See Photo
2A	1	33+50	LT,CL	10/20/2011		15,16,24	1	Additional BMP's needed. See Photo
1C	1	21+00	LT	10/6/2011	T = 10-6-11	10,12,15,35,41	FM	Monitoring BMP's in place.
1B	1	22+00	RT	10/17/2011		41	FM	Backfilling RCBC in progress.
1A	1	21+50	RT	10/17/2011		41	FM	Backfilling RCBC in progress.
1	1	14+14	LT	10/20/2011		22,35	FM	Weekly cleaning will be required, until further notice.
Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments

EROSION AND SEDIMENT CONTROL MEASURE CODES

1	Temporary Silt Fence / Filter Barrier	15	Temporary seeding with Mulch	29	Excess Dirt Removed from Rdwy. Daily	М	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	1	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	w	Too Wet to Work Conditions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, riprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42	Bridge Construction	Other (O#3):	
				43	Stream Realignment		

57		
1	N.	
3	1.01	
ÇURI		
	 	
0/		

State/US Route or Road Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:	
------------------------------	------------------	------------------------	---------------	--------------------	--

Date _____10/20/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
5C	1	44+00	LT	10/20/2011		16,24	FM,(₩)	Weekly cleaning for stream crossing required. (BMP's needed @ New Channel Realignment. See Photo)
6	1	56+00	LT	10/20/2011		16, 32	FM	Pond has been drained.
7	1	60+00	RT	10/17/2011		16	FM	Actively clearing and mulching.
8A	1	73+00	RT	10/20/2011		16,24,42	FM	Weekly cleaning for stream crossing will be required, until further notice.
8B	2	75+50	RT	9/29/2011		16,24,35,41	S	Currently Stable, Monitoring BMP's.
8C	1	71+00	LT	10/20/2011		16,42	FM	Active construction zone.
8D	2	75+50	LT	10/3/2011	T = 10-3-11	16,35,42	FM	Monitoring BMP's. Weekly watering required until seed establishes.
8E	1	71+50	LT					The area has not been disturbed.
9A	2	80+00	RT	9/29//11	T = 10-3-11	6,15,33,35	FM	Weekly watering required until seed establishes.
9В	2	80+00	LT	9/29//11	T = 10-3-11	15,16,17,,35	FM	Weekly watering required until seed establishes.

EROSION AND SEDIMENT CONTROL MEASURE CODES

1	Temporary Silt Fence / Filter Barrier	45	T	9292			
		15	Temporary Seeding with Mulch	29	Excess Dirt Removed from Rdwy. Daily	M	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen		Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	ī	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	w	Too Wet to Work Conditions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, riprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	35	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road		
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade			Other (O#2):	
		20	willeral Aggregate base off Subgrade	42	Bridge Construction	Other (O#3):	

CONDITION CODES

	VOE T	HES	.	
E.	2			
	85	47		:
**		ме кс 796 *	3/.	

State/US	Route or	Road Name:	- 1
----------	----------	------------	-----

Wolf River Blvd.

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

Date	10/20/2011

	No.	Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Stabilization and Code T = Temp. P = Perm.	EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
9C	2	79+50	LT	9/29/2011	T = 10-03-11	15,16,20,33	FM	Weekly watering required until seed establishes.
10A	2	85+00	RT	9/29/2011		15,16,35,41	FM	Currently active construction site. Sand bag upstream, remove daily during construction.
10B	2	85+00	RT	9/29/2011		15,16,35,41	FM	No work done in this area on inspection date.
10C	2	85+50	LT	9/29/2011		10,15,16,35,41	FM	No work done in this area on inspection date.
10D	2	84+50	LT	9/29/2011		10,15,16,35,41	FM	No work done in this area on inspection date.
11A	2	92+50	RT	10/20/2011		35,41	FM	Active construction zone.
11B	2	92+50	LT	10/6/2011		10,32,35,41	FM, W	Remove floatables. See photo
11C	2	92+00	LT	10/6/2011		10,32,35,41	FM,W	Remove floatables. See photo
	1	11+28	LT	10/20/2011		19,35	FM	Daily cleaning is required, until further notice.
	1	13+40	RT	10/20/2011		23,29,30	FM	Daily cleaning will be required, until further notice.
	1	107+75	CL N AND SEDIME	10/20/2011	IEASURE CODES	23,29,30	FM	Daily cleaning will be required, until further notice. CONDITION CODES

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier 1 Temporary Seeding with Mulch 29 Excess Dirt Removed from Rdwy. Daily M Maintenance 2 Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) Temporary Slope Drain 17 Erosion Control Blanket 31 Ditch Liner R Replacement Needed 4 Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM **Future Maintenance** 5 Brush Barrier 19 Catch Basin / Storm Inlet Protection Temporary Silt Fence with Backing 33 C Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure 34 Enhanced Silt Fence Increase Measures 7 Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Sediment Release Concrete Washout, other pollution Issues SR Temp Sediment Filter Bag / Dewatering 10 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Sheet Pilling Other (O31): 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O#2): Permanent Seeding with Mulch or Sod Mineral Aggregate Base on Subgrade 42 Bridge Construction

Other (O#3):



State/US Route or Road Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:	
0.00 min					

Date 10/20/2011

Outfall Name	Rain	Approx.	LT, RT or	Date Last	Date of Stabilization	Existing EPSC	Current	
or Station No.	Gage	Station No.	Centerline	Disturbed	and Code	Control	Condition	Corrective Action(s) or Comments
(Existing	No.	From / To			T = Temp.	Measure	Codes	
Structure)					P = Perm.	Codes*		
	32-4-3							Daily cleaning will be required, until further
* 109+51	2	East side of WRB	RT	10/20/2011		19,22	FM	notice.
100000000000000000000000000000000000000		South side of						Daily cleaning will be required, until further
* 109+11	2	Farmington	RT	10/20/2011		19,22	FM	notice.
		North side of	2722	No Connect State		85 da Niciana	Destrophic Destroy	Daily cleaning will be required, until further
* 12+80	1	WRB	LT	10/20/2011		19,22	FM	notice.
		Walking Trail						
	1	36+00	LT	7/20/2011	T = 7-20-11	5,35	S	Currently stable, Monitoring BMP's
1	_					100		
	1	Sta. 29+50 Slope	LT	7/20/2011	T= 9-01-11	16	S	Currently stable.
		Sta. 13+40 -						Haul roads dampened frequently for dust
		Sta. 107+75	LT, RT or CL	10/13/2011		30	FM	control, until further notice.
				N7 55				
	2	76+50 - 103+46	RT	9/29/2011	T = 10-03-11	15,16,35	FM	Weekly watering required until seed establishes.
	2	00.50 407.00		0/00/0044	T 40 00 44			
<u> </u>	2	92+50 - 107+00	LT	9/29/2011	T = 10-03-11	15,16,35	FM	Weekly watering required until seed establishes.
	1	0.75		40/00/0044		40.00		Daily cleaning will be required, until further
		6+75	LT	10/20/2011		19,22	FM	notice.
	1	27+00	RT	10/3/2011	T= 10-03-11	15,16	s	Currently stable, Monitoring BMP's
	1	34+00	RT	8/25/2011	T= 8-25-11	16	S	Currently stable, Monitoring BMP's
EROSION AND SEDIMENT CONTROL MEASURE CODES CONDITION CODES								

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier 15 Temporary Seeding with Mulch Excess Dirt Removed from Rdwy. Daily M Maintenance 2 Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 **Erosion Control Blanket** 31 Ditch Liner R Replacement Needed Rock Check Dams 18 Flexible Channel Liner Rock Silt Screen FM **Future Maintenance** Brush Barrier 5 19 Catch Basin / Storm Inlet Protection Temporary Silt Fence with Backing C Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure 34 **Enhanced Silt Fence** Increase Measures 7 Straw Bale Check 21 Riprap Energy / Velocity Dissipater Sediment Tube W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release 10 Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized Polyethylene Sheeting 11 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Other (O31): Sheet Pilling 13 Geotextile 27 Other (O#2): Preserve Natural Resource / Buffer Zone 41 Haul Road 14 Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Subgrade **Bridge Construction** Other (O#3):

EPSC Inspection



0 id Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:

Date _____ 10/20/2011

Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
1	21+33 - 26+00	LT	10/10/2011	T = 10-6-11	15,16,35,41	FM	Weekly watering required until seed establishes.
1	21+33 - 26+00	RT	10/10/2011	T = 10-6-11	15,16,35,41	FM	Weekly watering required until seed establishes.
1	25+00	LT	9/29/2011	T = 10-6-11	15,16,33,35,41	FM	Currently stable, monitoring BMP's.
1	25+00	RT	9/29/2011	T = 10-6-11	15,16,33,35,41	FM	Currently stable, monitoring BMP's.
1	27+50	RT	10/6/2011	T = 10-6-11	15,16,33,35,41	FM	Currently stable, monitoring BMP's.
1	31+90	RT	9/29/2011	T = 10-6-11	15,16,35	FM	Currently stable, monitoring BMP's.
1	15+60	RT	9/15/2011	T = 10-6-11	15,16,33,35	FM	Currently stable, monitoring BMP's. Weekly watering required until seed establishes.
	North side of WRB	LT	10/13/2011		19,22	FM	Daily cleaning will be required, until further notice.
1	23+00 - 26+00	RT	9/29/2011	T = 10-6-11	33,41	FM	Currently stable, monitoring BMP's.
	Gage No. 1 1 1 1 1 1 1 1	Gage No. From / To 1 21+33 - 26+00 1 21+33 - 26+00 1 25+00 1 25+00 1 27+50 1 31+90 1 15+60 North side of WRB	Gage No. Station No. From / To Centerline 1 21+33 - 26+00 LT 1 21+33 - 26+00 RT 1 25+00 LT 1 25+00 RT 1 27+50 RT 1 31+90 RT 1 15+60 RT North side of WRB LT	Gage No. Station No. From / To Centerline Disturbed 1 21+33 - 26+00 LT 10/10/2011 1 21+33 - 26+00 RT 10/10/2011 1 25+00 LT 9/29/2011 1 25+00 RT 9/29/2011 1 27+50 RT 10/6/2011 1 31+90 RT 9/29/2011 1 15+60 RT 9/15/2011 North side of WRB LT 10/13/2011	Gage No. Station No. From / To Centerline Disturbed and Code T = Temp. P = Perm. 1 21+33 - 26+00 LT 10/10/2011 T = 10-6-11 1 21+33 - 26+00 RT 10/10/2011 T = 10-6-11 1 25+00 LT 9/29/2011 T = 10-6-11 1 25+00 RT 9/29/2011 T = 10-6-11 1 27+50 RT 10/6/2011 T = 10-6-11 1 31+90 RT 9/29/2011 T = 10-6-11 1 15+60 RT 9/15/2011 T = 10-6-11 North side of WRB LT 10/13/2011 T = 10-6-11	Rain Gage No. Approx. Station No. From / To LT, RT or Centerline Date Last Disturbed Stabilization and Code T = Temp. P = Perm. EPSC Control Measure Codes* 1 21+33 - 26+00 LT 10/10/2011 T = 10-6-11 15,16,35,41 1 21+33 - 26+00 RT 10/10/2011 T = 10-6-11 15,16,35,41 1 25+00 LT 9/29/2011 T = 10-6-11 15,16,33,35,41 1 25+00 RT 9/29/2011 T = 10-6-11 15,16,33,35,41 1 27+50 RT 10/6/2011 T = 10-6-11 15,16,33,35,41 1 31+90 RT 9/29/2011 T = 10-6-11 15,16,33,35,41 1 15+60 RT 9/15/2011 T = 10-6-11 15,16,33,35 North side of WRB LT 10/13/2011 T = 10-6-11 15,16,33,35	Rain Gage No. Approx. Station No. From / To LT, RT or Centerline Date Last Disturbed Stabilization and Code T = Temp. P = Perm. EPSC Control Measure Codes* Current Condition Codes* 1 21+33 - 26+00 LT 10/10/2011 T = 10-6-11 15,16,35,41 FM 1 21+33 - 26+00 RT 10/10/2011 T = 10-6-11 15,16,35,41 FM 1 25+00 LT 9/29/2011 T = 10-6-11 15,16,33,35,41 FM 1 25+00 RT 9/29/2011 T = 10-6-11 15,16,33,35,41 FM 1 27+50 RT 10/6/2011 T = 10-6-11 15,16,33,35,41 FM 1 31+90 RT 9/29/2011 T = 10-6-11 15,16,33,35,41 FM 1 15+60 RT 9/15/2011 T = 10-6-11 15,16,33,35 FM North side of WRB LT 10/13/2011 T = 10-6-11 15,16,33,35 FM

EROSION AND SEDIMENT CONTROL MEASURE CODES

1	remporary Sitt Fence / Filter Barner	15	Temporary Seeding with Mulch	29	Excess Dirt Removed from Rdwy. Daily	М	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	1	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	w	Too Wet to Work Conditions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, riprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	s	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Sub grade	42	Bridge Construction	Other (O#3):	

CONDITION CODES




Outfall 2A Sta. 33+50 LT,CL Additional BMP's Needed. (I)



Outfall 2B Sta. 35+50 BMP's Needed (FM)




Outfall 4 Sta. 40+00 RT Re-Hydro Seed disturbed area and Stabilize Slope. (I,RO)




Outfall 4 Sta. 40+00 RT Stabilize Slope. (I,RO)



City of Germantown 1920 S. Germantown Road Germantown, TN 38138



Outfall 11B Sta. 92+50 LT. & Outfall 11C 92+00 LT. Remove Floatables from flow line. (FM, W)





City of Germantown 1920 S. Germantown Road Germantown, TN 38138